## Publication No. 84-e32

JOHN SPELLMAN Governor



WA-15-0020

#### STATE OF WASHINGTON

#### DEPARTMENT OF ECOLOGY

7272 Cleanwater Lane, LU-11 • Olympia, Washington 98504 • (206) 753-2353

MEMORANDUM September 4, 1984

To:

Bill Yake

From:

Joe Joy

Subject: Eagle Harbor Facilities Tours and Historical Review

### INTRODUCTION

A series of environmental investigations by the Washington State Department of Ecology (WDOE) and the U.S. Environmental Protection Agency (EPA) has been undertaken to discern the extent and source(s) of polynuclear aromatic hydrocarbon (PNA) and phenolics contamination of Eagle Harbor sediments (Joy, 1984). As part of this effort, three commercial facilities were toured by WDOE personnel.


The three commercial facilities were selected by WDOE and EPA staff during an April 2 meeting (Cunningham, 1984). These facilities were thought to be potential sources of PNAs and/or phenolics.

The three facilities chosen were (Figure 1):

- The Wyckoff Company a pole and piling preserving plant
- The Washington State Ferries a ferry maintenance and repair yard
- Diesel Oil Sales a diesel storage facility

On April 12, Art Johnson and I accompanied Dave Wright and Craig Baker of the Northwest Regional Office (NWRO) on tours through these three facilities. The purpose of the visits was to review existing and historical operations and waste-disposal practices with facility managers, and to identify any practices contributing to the PNA and phenolics problems in Eagle Harbor.

In addition to the on-site tours, I have reviewed NWRO files and other materials pertaining to the facility sites and Eagle Harbor in general. The purpose of this review was to identify any past events that may have contributed to the current contamination problem in the harbor.



The purpose of this memorandum is to combine three previously separate memoranda for expanded distribution. The findings of the tour and historical review in this memorandum were previously presented and discussed in the following memoranda:

- Part I: The Wyckoff Co. August 9, 1984
- Part II: The Washington State Ferries Maintenance Facility -August 15, 1984
- Part III: Diesel (Standard) Oil Sales August 20, 1984.

Only minor changes have been made to the original memoranda with their inclusion in this report; e.g., consolidation of references and renumbering figures.

### PART I: THE WYCKOFF COMPANY

## FINDINGS


On April 12, 1984, our WDOE party was met by Marc Walker, Don Johnson, and Chuck Stoddard of Wyckoff for the tour. Mr. Walker is the Eagle Harbor plant foreman, while Messrs. Johnson and Stoddard are from Wyckoff's area offices in west Seattle. The Wyckoff Company representatives explained the operation of the plant and some of the changes made in waste treatment processes over the years.

## Layout and Operations

The Wyckoff Company Eagle Harbor facility occupies approximately forty acres on Bill Point (Figure 2). Site elevation is approximately ten feet above sea level. Most of the facility is located on pervious, fill materials; however, paved roads and surfaces are present in the log storage area. The facility has approximately 0.8 mile of shoreline that has been reinforced and improved over the years. In addition, the Wyckoff Company owns the tidelines to extreme low tide (approximately -4.5 feet), and has a twelve-year lease on bedlands in its log boom storage and docking areas (DNR, 1984).

The facility includes areas for the following operations (Figure 2):

- log rafting
- log peeling
- log storage
- log treatment
- chemical storage and wastewater treatment
- shipping
- aromatic oil and creosote unloading



2: The wyckoff Co. site plan, Eagle Harbor, WA. Figure

In general, logs move from delivery and storage operations in the western portion of the facility, to treatment and shipping operations in the northeastern portion.

Creosote is unloaded from barges every twelve to fifteen months and transferred by pipleine from the westernmost dock to the storage tanks (Figure 2). However, no shipments of creosote had been received for six years. Aromatic oil is transferred from the eastern (Milwaukee) dock via pipeline to storage tanks. The oil is mixed with solid pentachlorophenate salt which arrives by truck.

Figure 3 shows the northeast portion of the facility in more detail. The structures located here that are directly associated with wood-preserving operations include:

- creosote and pentachlorophenol (PCP) storage tanks
- two deep wells
- the boiler house
- the engine room and retorts
- the wastewater control system: separators, pumps, and tanks

Poles and pilings had not been treated at the plant since March 1982<sup>1</sup>. Plant activities had been reduced to receiving, peeling, and storing logs. These logs are either shipped to the Wyckoff's West Seattle plant or remain stacked in the yard until treatment operations are resumed at Eagle Harbor.

The facility uses the Boulton method of wood preserving. Both creosote and pentachlorophenol are used in this pressure treatment. Briefly, the peeled logs are received into retorts where they undergo the following:


- an initial heating-vacuum phase (while being immersed in preservative) to remove moisture and natural oils from the logs
- a preservative pressure phase
- a second vacuum phase to return preservative to the storage tanks

The logs are moved out of the retorts onto the transfer table area (Figure 3). Here they are allowed to dry. Then they are either restacked and await shipment by barge, or they are placed in log boomed storage.

#### Waste Treatment

Process wastewater at Wyckoff is generated in two areas: (1) the retorts, or (2) the boilers. The wood-preserving area and the boiler area have separate wastewater treatment systems. Schematic diagrams supplied by Wyckoff describe the two systems (Figures 4 and 5).

 $^{
m 1}$ Treatment at the Eagle Harbor facility was resumed on May 15, 1984.



The process effluent from the Boulton-type wood-preserving process contains:

- Water vapor from the wood
- Wood sugars and oils
- Low boiling fractions of preservative

These are drawn-off the retorts by vacuum as vapor after the logs have been immersed in heated preservative.

At the Wyckoff plant, a system for pentachlorophenol and a system for creosote residue vapors are present (Figure 4). The systems are very similar in construction. Briefly, the steps are these:

- 1. The vapors are condensed in the condensers using cooling water from the cooling water evaporation tank.
- 2. The condensed wastewater is sent to a "hot well" where the volume is measured.
- 3. The oil and water phases are separated using a combination of settling (high) tanks, API separators, and plate filters (with oil absorbant).
- 4. The oil phase is returned to respective preservative storage tanks.
- 5. The water phase is combined with the cooling water returning from the condensers.
- 6. This combined water is pumped to the cooling water evaporation tank and recycled through the condensers as necessary.

Sludges accumulate in the separators, tanks, and filters. These sludges are placed in 55-gallon drums and stored in a covered area on a concrete slab next to the boiler building. The drums are periodically taken to a hazardous waste disposal site (Arlington, Oregon).

Most of the preservative from the retorts and all retort drippings do not enter the wastewater treatment system. Instead, they are drawn directly into the preservative storage tanks.

The boiler water is used to generate steam. The steam heats the preservative and applies pressure in the retort chambers. The retorts are jacketed so that no steam is directly in contact with preservative.

Blowdown is created in the two boilers at the plant, and this effluent is drawn-off and treated in the blowdown disposal system (Figure 5).

Blowdown contains boiler treatment chemicals and concentrated minerals and salts from the make-up water.

BULKHBAD




Figure 5: Schematic diagram of the boilor blowdown treatment system at the trigology Drawn by D. Johnson, Wyckoff Co, 481.

Treatment consists of the following:

- 1. The solids in the bottom blowdown are initially separated from the water using a settling tank.
- 2. Water from this initial separation is added to the constant blowdown water.
- 3. Flocculants and pH-adjusting chemicals are added and mixed with the combined dowdown water.
- 4. Floc and solids are settled-out in two additional tanks.
- 5. The water phase is drawn off the top of the settling tanks and piped to cooling water evaporation tank.

The wood-preserving effluent system is relatively new. The old system discharged into a sump (Figure 3). Transfer from the old system to the new, closed system was accomplished in late 1981 or early 1982.

Modification of sludge disposal was also made in 1981. Prior to that time, sludge was buried on site (? - 1971), or received by a disposal company and hauled to the county landfill (1971-1981).

Because wood-preserving activities had been suspended for some time at the site, the wastewater systems were not in operation during the tour. Messrs. Walker and Johnson told us the system piping had been cut and drained to protect lines and pumps from freeze damage. Dave Wright observed that the boiler blowdown collection system had been disconnected (Wright, 1984). In addition, a PVC line at the cooling water evaporation tank ancilliary spray system pump was cut. There seemed to be some confusion as to the location of the other end of the line and its destination. The line finally chosen was too small in diameter and led over the bulkhead.<sup>2</sup>.

During the tour, we noted the processing area, including the transfer table, tank areas, and retorts, was not sealed and contained. No stormwater collection system is present except a diversion drain along the southern border of the property. At other wood-preserving facilities, process areas are contained to prevent the escape of spilled preservative (S.W. Regional Office Staff, 1984). Chronic spills, especially onto the transfer table, have created severe subsoil contamination at other facilities (Thompson, Wardrop, et al., 1978; S.W. Regional Office Staff, 1984).

### Historical Review

Several documents were reviewed to construct a historical account of activities and events at the Wyckoff site. A visual aid was constructed to help summarize the major points of the compilation (Figure 6). A detailed history of the site follows:

<sup>&</sup>lt;sup>2</sup>The line from the cooling water evaporation tank auxiliary pump has been removed entirely, and its purpose was unknown (Stoddard, 1982).

pre- 1940's	1940'5	1950's	5,0961	5,0261	2,0861
OWNERSHIP OF SITE:  1905-PIKC(Pile?) Preserver Co.  Pacific Creosoting Co.  West Coost	VERSHIP OF SITE: 5- Pikc (Pile?) Persorver Co. Pacific Crepsoting Co. West Coast Wood Preserving Co.		. Boxter - Wyckeff Co	· Wyckoff Co.	
CHANGES IN LAYOUT & OPERATIONS:  Bulap and asphalt wrapping of poles  Cressote Treatment  Fill and dredging on east shoreling.	anges in Lavout ; Operations: inlep and asphalt wrapping of poles trostot Tratment Fill and dredging on east shoreline ( . Fill and dredging on east shoreline (	(plant rebuilt ca. 1.920's?) d engine room ato present	g of poles cast shoreline (plant rebuilt ca. 1.920's?) . Retort and engine room ato present location (1945-1946?)	1946?> . Regrading of log s	storage area
CHANGES IN WASTE	CHANGES IN WASTEWATCR TREATMENT OPERATIONS:	OPERATIONS:		J	
<i>t</i> ~°	. Oil separator in	. Oil separator in use for retort drippings; o . Boiler water through separate outfall . Process	. Oil separator in use for retort drippings; offlicent through coke filter and dischanged via outfall totractor.  . Boiler water through separate outfall.  . Process efflicent to sump; outfall eliminated.  process wastewaters	e filter and dischanged ,; outfall elininated	via outfall tolocular.  . Closed system for process wastewaters
SLUDGE OPERATIONS:		rs bulkhead fill and	ic Sindqes used as bulkhead fill and buried alsewhere onsite	voried absendere onsite.  Sludges eroding from bolkhead fill; moved farther back onsite	wed farther back on it
				· Sivages taken to local landfill · Some old sludge removed to · Sludges and sent- hazandous	Studges taken to local landfill  Some old studge removed to landfill  Studges collected and sent to hazandoss waste
INVESTIGATIONS.		Report of domping " 1410 p . Oil stourstor	site  Report of domping of 1410 ppm of phenols in process water going to outfall  Soil separator in need of repair  Soil borings and consultant work.  A Various reports of oil spills, and oil sheen on water and sectionaries	oping to outfall soings on soil sorings on soil soings or soil shear or	site . Well testing consultant work
FIGURE 6: Major,	historical points	of interist concen	Elquete: Hajor historical points of interest concerning the wyckoff Co. site, Eagle Harbor, with	. Co. site, Eagle L	tarbor, w.A.

Date		References
1905	Pile (or Pike?) Preserver Company moves to Bill Point after one year at Port Madison. Poles wrapped in burlap and asphalt. Name soon changed to Pacific Creosoting Company.	Merriott, 1941 Bowen, <u>et al</u> ., 1971
ca 1917	An earlier bulkhead with a wing wall is shown on maps of the site (Figure 3).	Dehn, 1972
1929	Pacific Creosoting Company applies for Corps of Engineers permit to dredge, bulkhead, and fill.	Aldis, 1984
1942	Deep well drilled to 813 feet (Figure 3). Casing perforated at 90 to 105 feet and at bottom. Artesian. One previous drilled well to 500 feet also artesian.	Sceva, 1957
1944	Aerial photo of the area shows shoreline and dock facilities similar to their present shape. Ponds situated where retorts currently stand. Creosote tank #6 present (Figure 3).	Army Service Map, 1944
1947	Inspector from the Washington State Pollution Control Commission (WPCC) made return inspection of West Coast Wood Preserving Coplant plan. He finds plant clean and precautions taken against oil spills into Eagle Harbor. Also, less oil in harbor because treated logs are shipped by barge rather than rafting.	Young, 194/
1952	Department of Fisheries receives a report of night dumping of "cook liquor." Sand covered with oil at times.	Fitzgerald, 1952
	WPCC engineer investigates above complaint. Reports:	Jones, 1952a
	(1) Plant has oil separators and condensers to prevent loss of material.	
	(2) Slight oil slick in vicinity of out- fall due to small quantities of naph- thalene and phenol.	
	(3) Spill of creosote "a year or two ago" during tanker unloading operations.	
	(4) Present company waste practices	

WPCC engineer describes plant operations.

Jones, 1952b

- Vapors from retorts condensed and retored to creosote tank
- Wastes from drip pans under retorts pass through oil separator, coke filter and then discharged to Puget Sound.
- WPCC inspector reports good operation of Nie plant. Oil separator needs "replacement of chains on the skimming pipes."

Nielson, 1953

WPCC, 1956

1956 WPCC Waste Discharge Permit No. 387 allows 1 MGD of cooling and effluent wastewater discharge from outfall. Effluent shall not exceed 10 ppm total oils and 1 ppm phenols.

r not ols. Anon, 1957

1957 WPCC inspector takes oil separator composite sample and cooling water grab sample. 1410 ppm phenols in composite sample. 0 ppm phenol in grab. Separator flow 0.004 MGD (11 gals/min for 6 hrs/day); cooling water flow 0.95 MGD. Inspector reports separator and cooling water not mixed. Beach is oiled adjacent to outfall.

A 40' x 12' x 6' treated piling lined pit is constructed in the sand fill to dump effluent from oil separator. Water seeps through sand, and oil is skimmed off at regular intervals. Sludges are dug-out periodically and deposited on site.

Knox, 1957; Huntley, 1957; Knox, 1958; Knox, 1962

1959 Constant oil slick is reported off West Coast Wood Preserving Company plant. Shop foreman at plant believes it's from chronic oil spillage at the site.

Nielson, 1959

Baxter-Wyckoff Company is new owner of the Eagle Harbor facility.

Bainbridge Review, 1959

WPCC inspector notes that bulkhead is in need of repair. Oil separator sludges had been used in the past for fill behind bulkhead. Inspector suggests sludges should be deposited farther away. Waste Discharge Permit No. 1344 reiterates inspector's suggestion.

Knox, 1961

A routine inspection is made of facility while investigating a reported oil spill in Winslow. Plant is suspect, but no oil is seen on shoreline.

Knox, 1953


1971 Waste Discharge Permit No. 3680 for the Wyckoff Company:

WDOE, 1971

- 0.02 MGD wastewater allowed to be discharged to groundwater via seepage basin.
- Sludges and waste oils deposited are transferred to portable steel containers and given to qualified disposal company.
- Treated logs may be deposited in log pond after preservative drains, cools, and dries.
- Washington State Department of Ecology (WDOE) and Environmental Protection Agency (EPA) request the Wyckoff Company to investigate oil seepage problem. The Wyckoff Company has nine test borings and one well drilled (Figure 7), and hires two consulting firms: Harbinger, Inc., and CH<sub>2</sub>M Hill. Test borings and well were made to 30'. Visual observations were made of materials extracted. They revealed:

Dehn, 1972; Pacific Testing Lab, 1972; Allworth, 1972

- Creosote at some stratum in all borings.
- Odor of creosote or creosote at 30' in all but one boring (#4).
- Boring #4 had clay layer at approximately 24' with creosote above and very little below.
- Most borings had soils with high or moderate permeabilities to 30', and no sign of change.
- Water table at approximately 7.5'.
- "During high tides, a 1/8" to 1/4" layer of creosote floated in the well" (test well drilled near boring #1).
- Groundwater appears to be perched "higher than would normally be expected."



In addition to borings and the test well, the following operations were completed:

- Sludge deposit A (Figure 3) was removed and taken to a municipal landfill.
- Leaks in the creosote fill line were detected; the line was drained and capped.
- Tanks Nos. 6 and 4-A (Figure 3) were checked for leaks; none were detected.
- Several holes were dug to 7' depth in search of sludge deposits.
- A depuration (air flotation cell) unit was tested to separate creosote from groundwater; test results were discouraging.
- Water was analyzed from test well: 130 ppm total oils, pH 7, 3.2 ppm phenol.
- A new phenol lab method was found because of "illogical" results in creosote-water samples.

Recommendations from these studies were:

Adam, 1972; Dehn, 1972; Allworth, 1972

- Install shallower well to get higher concentration of creosote; then retest depuration unit.
- Experiment with other chemical methods of creosote and phenols removal from groundwater; e.g., activated carbon, sorbents, ozone, potassium permanganate.
- Drill more borings and wells to obtain better hydrogeologic data, and define extent of contamination.
- Test other tanks (walls and bottoms) and lines for leaks.
- Check tank sludges for corrosive activity.
- Excavated other sludge deposit (#B) and search for others.

Dehn, 1972; Adam, 1972; Johnson, 1972; Allworth, 1972; WDOE, 1971

In addition, CH<sub>2</sub>M Hill briefly discussed alternate control methods:

- Bentonite or sheet pile barriers.
- Interceptor wells.
- Major excavation of contaminated materials.

Wyckoff reported these findings and recommendations to WDOE and indicated they would go ahead with additional tank testing.

Adam, 1972

The Wyckoff Company renews its 12-year lease of bedlands for the purposes of log boom storage and docking facilities. An additional note is that the company owns the tidelands to the extreme low water.

DNR, 1980

In response to queries by the Kitsap Co. Assessors office concerning the request by Wyckoff for reductions of assessed value of property because of soils, groundwater contamination, Baker responded:

Baker, 1981

- Seepage of creosote continues despite efforts to control.
- (2) A new discharge permit is being workedout.
- (3) Testing of soils and possible removal of those that are contaminated will be made if the Wyckoff Co. should leave.

Waste Discharge Permit 3680 for the Wyckoff WDOE, 1981 Company:

- S1: discharge 0.005 MGD to groundwater until November 1981.
- S2: no discharge of effluent to groundwater permitted.

- S4: (a) prevent entry of solid waste material into state ground or surface water.
  - (b) prevent leachate entry into same without providing all known available and reasonable methods of treatment.
  - (c) plan to handle solid wastes as per RCRA.

The Wyckoff Company notifies WDOE that ground sump will be eliminated by December Ĭ981.

Johnson, 1981

1983 A draft report by a consultant hired by EPA Fuentes, 1983 suggests Wyckoff site should be switched from active to inactive status as a hazardous waste site. The reasons for this recommendation are:

- Only a small quantity of sludge (hazardous waste) generated (<2000 lbs/yr).
- Effluent system is now closed loop.
- WDOE sees no groundwater contamination problem.

### DISCUSSION AND CONCLUSION

The main points of interest obtained from the site tour and historical review of the Wyckoff site are:

- The current wastewater systems are designed to eliminate the discharge of process and boiler effluent to surface and groundwater.
- The past wastewater system discharged effluents with high concentrations of phenols and oils into the groundwater (1957-1981) and Puget Sound (1946?-1957).
- The site has undergone at least two major reconstructions (1920s, 1940s), and much fill material has been added. The older methods of operation and their location on the site are uncertain.
- Incidental spillage in the treated log transfer and storage, and tank and process areas have been and continue to be uncontrolled.
- Some sludge disposal areas have been identified and have been removed from the site; however, some sludge deposits probably remain.
- Intertidal and subtidal areas beneath the creosote unloading dock and treated log storage boom area may contain treatment compound residuals from spillage.
- Creosote-like materials have been detected in subsoils at many points within the site to a depth of at least 30 feet.
- Seepage of light fraction oils into Puget Sound has been a chronic problem for at least 25 years.

These main points strongly suggest that the subsoils onsite and in adjacent shorelands have high concentrations of oils and phenols. Although the plant has not been preserving materials since 1982, chronic oil seepage from the site has continued. This seepage, in the form of oil slicks and discolored intertidal sediments, has been recognized for many years.

The following questions remain concerning the contamination at the Wyckoff site:

- 1. What are the quantities and characteristics of preservative materials in the subsoil and groundwater on the site?
- 2. Are there current sources of these materials contributing to further subsurface contamination?

- 3. To what extent are the materials moving off the site, how do their chemical characteristics change during this transport, and where will be their final destination?
- 4. To what extent do these materials constitute an environmental hazard?
- 5. If a hazard is present, what remedial actions can be taken to minimize or eliminate this hazard?

Many of these questions remain unanswered. However, the information from the work accomplished in this report may give some "clues" to questions 1 and 2. Much more investigation on-site and off-site would be necessary to satisfactorily answer all the questions.

With regard to question 1, some of the following data are available:

- Creosote-like oils were detected in some test bore holes to at least 30 feet (Allworth, 1972).
- In all but one test hole no impermeable layer was found for at least 30 feet (Allworth, 1972).
- Test bore #2 yielded a "heavy concentration of creosote" at 19 1/2 to 20 feet, just above "tight silt and fine sand" layer 1.5 feet thick; creosote was again detected below this layer (Pacific Testing Lab., 1972).
- The 800-foot well on site which is screened at 95 feet to 105 feet, has no creosote materials present (EPA, 1984a).

Creosote is a multi-phase oil having constituents lighter and heavier than water. These constituents will separate-out vertically and horizontally according to chemical and hydrogeologic factors; e.g., soil permeability, groundwater direction and rates of movement, adsorption of contaminants to soil materials, biochemical degradation, and chemical solubilities. For example, creosote seemed to be retained in a heavier concentration above the low-permeability silt layer mentioned above than in gravel and coarse sands above and below the silt layer. Additionally, Allworth (1972) noted a "creosote oil" floating on the water table.

The nature of creosote, the permeability of the subsoils, and the chemical results of the well test suggest that the heaviest concentrations in most of the areas explored in 1972 may be found below 30 feet, but shallower than 95 feet.

With regard to the second question, there are also some data available from this report:

Some testing of tanks and lines, and buried sludge removal was accomplished in 1972 (see 1972, above).

- Wastewater effluent is now entirely contained within a closed system and no longer discharged to groundwater or surface water.
- Should the plant resume full operations, some further control measures could be made to prevent further contamination.

It is unclear from the record if all tankage and lines have been tested. For example, the iron content tests suggested by CH<sub>2</sub>M Hill in 1972 for bottom leaks may have been acomplished as planned by Wyckoff (Adams, 1972). During the 1984 tour, Wyckoff personnel were uncertain of line locations from older plant operations, so that lines may exist which have not been tested. In addition, sludge may have been removed from under the penta-mix building in addition to the deposit found south of tank #4A (Figure 3). However, the Wyckoff personnel were uncertain of this when asked in April of 1984.

Finally, from observations made on the tour, some actions could be taken to reduce contamination if the plant resumes normal operations. The areas in need of attention are:

- The treated log transfer and storage area.
- The tank storage and process area.
- The process wastewater treatment system.

Immediately after being treated in retorts, logs are moved through the transfer table to on-site storage areas (Figure 3). Freshly treated logs contain residuals of preservative in wood cracks. This preservative drips to the ground. As previously mentioned, heavy contamination of subsoils in the transfer table/treated log storage areas has been detected at other wood-preserving operations (Thompson, Wardrop, et al., 1978; Stoddard, 1984; S.W. Regional Staff, 1984).

Tank storage and process areas are also prone to accidental spillage from leaking valves and pumps. Any liquid material spilled to the ground would migrate downward through the highly permeable soils at the Wyckoff site.

The steps taken by Wyckoff personnel to protect the process wastewater treatment system from freeze damage are appropriate. However, the confusion observed during the tour concerning the proper reconnection of line from the cooling water tank auxiliary spray pump is distressing. Plant personnel should be intimately familiar with the wastewater flow system.

The following recommendations are made to ensure that accidental spillage of treatment compounds does not continue to occur when the plant resumes operations:

1. The treated log transfer and storage area and process and storage areas should be lined with an impermeable material. Preservative product and stormwater from these areas should be collected and treated before discharge into surface or groundwaters.

2. The process wastewater treatment system should be thoroughly tested and inspected by plant personnel with intimate knowledge of the system design. Other personnel should be instructed in the proper maintenance of the system and emergency response measures.

The Wyckoff Company and former companies at the site have had a documented attitude of cooperation with the WDOE, EPA, and before that, the WPCC. I see no change in the current attitude of the company personnel I have contacted, and I am confident of their continued cooperation.

# Part II: The Washington State Ferries Maintenance Facility

## FINDINGS

The WDOE party was met by Gene Nelson of the Washington State Ferries (WSF) Maintenance Facility. Mr. Nelson is the paint foreman. He showed us around the site and explained operational procedures. In addition, he had foremen of other areas explain their operations and field our guestions.

## Layout and Operations


The WSF Maintenance Facility is located on approximately three acres on the north shore of Eagle Harbor (Figure 1). The facility is used for routine repair and maintenance of the state's ferry fleet. The facility includes (Figure 8):

- A carpenter shop
- A machine shop
- A paint, solvent, and oil storage area
- Two docks with multiple berths

Repainting (above the water line), minor deck and cabin repairs, and minor engine maintenance and repair are performed at the facility. Major repair work and bottom-painting are contracted out to shipyards in Seattle or Tacoma.

Repainting involves removal of cracked and peeled coats of paint and application of new paint. Removal is all performed by scraping and chipping; no sand-blasting equipment is used. Paint sprayers are used to apply fresh coats of paint. All paint work is performed at the docking berths (Figure 8).

Deck, cabin, and mechanical repairs are accomplished by the machinists and carpenters. Parts are fabricated, repaired, or brought within specified tolerances using equipment in the shops. The machine shop also contains a sink for small plating jobs and a degreasing tank. A high pH inorganic solution is used for degreasing.



properties, Eagle Harbor, NTA. March 1984 USEPA, Figure 8: Site plan of washington State

## Waste Generation

The WSF facility has no wastewater treatment system or discharge. Wastes are disposed of through contractors. The waste types and contractors are:

- Bilge water Vacuum Tank Services, Seattle
- Spent degreaser Baker Septic Service, Winslow

The ultimate fate of these wastes was unknown.

The chemical storage area is covered and enclosed. However, the area has no containment curbing. Paint, degreaser, and lube oils are stored in original 10- to 55-gallon (approximate) containers.

## Historical Review

This historical review includes the WSF Maintenance Facility site and the adjoining areas occupied by a private boatyard to the west and a condominium complex to the east (Figure 8). The entire area of approximately fifteen acres was first a park and pavillion site (1890 to 1902), then a large shipyard (1902 to 1959) (Rowen, et al., 1971).

The name of the shipyard changed several times between 1902 and 1959 (Merriott, 1941; Bowen, et al., 1971):

- 1902-1916 -- Hall Bros. Marine Railway and Shipbuilding Co.
- 1916-1947 -- Winslow Marine Railway and Shipbuilding Co.
- 1947-1953 -- Commercial Ship Repair
- 1953-1959 -- Commercial Ship Repair, Div. of Pacific Car and Foundry

In 1903 the operation included: "a marine railway, machine shops, power house, sawmill and joiner loft for cutting ship timbers, a large gridiron, warehouse, and various other buildings and equipment" (Merriott, 1941). Other piers and smaller drydocks were added over the years (Bowen,  $\underline{et\ al}$ , 1971).

Tar, creosote, and oakum (oil-soaked hemp) were used in large quantities for wooden shipbuilding. For example, much of the one-building "the oakum shed" was used to soak, spin, and store oakum (Bowen, et al., 1971).

Many wooden and metal ships were built or repaired at the site. By 1916, 119 wood vessels had been built. Several metal boats were built during both world wars, including nine mine sweepers in 1942-43 (Bowen, et al., 1971).

Although it was common practice to pump oil-contaminated water from the bilges of ships directly into harbors and bays, only one documented reference was made of this concerning the Eagle Harbor shipyard. Nielson (1955) noted in his inspection report of the West Coast Wood Preserving Co. plant in Eagle Harbor, "The ship repair concern across the bay has often been accused of causing oil spills."

### DISCUSSION AND CONCLUSION

No potential sources of contamination to Eagle Harbor were observed at the WSF Maintenance Facility. However, past shipbuilding operations at the site (1902-1959) and adjoining areas may have contaminated the site with oils and phenolic substances.

Creosote, tar, and oil used in wood boatbuilding could have easily been spilled on nearshore and intertidal areas. Large volumes of these materials were necessary for the many wooden ships built and repaired at the shipyard since 1902.

Oils, greases, solvents, and paints common in shipyards fabricating metal vessels may have also been spilled at the site. Also, repair of such vessels involves pumping oil-contaminated water from bilges. Bilge discharges may have been discharged directly to Eagle Harbor.

Only one document specifically mentions the shipyard's reputation in regard to oil spills in the past (Nielson, 1955). However, the volume of business at the yard (1902-1959) and the technology available at the time suggest spills may have been a common occurrence.

In addition, the present boatyard to the west of the WSF facility may have had some more recent spills of liquid material. Aerial photographs from 1972 and analyzed by EPA (1984b) showed spill stains in the boatyard at that time. The yard has not been investigated by WDOE, but it should be included in any further investigation.

Further investigations at the WSF site and adjoining areas would be necessary to discern the following:

- The location, extent, and transport of any contamination in subsoils on the nearshore, intertidal, and subtidal areas.
- The environmental hazard posed by any contamination identified.

These investigations should be carried out based on results from the WDOE and EPA shellfish and sediment sampling performed in April (Joy, 1984).

## Part III: Diesel (Standard) Oil Sales

#### FINDINGS

The Diesel Oil Sales storage and transfer site was visited by WDOE personnel listed above. Observations of this relatively small site were made from outside a high enclosing fence. Messrs. Wright and Baker reviewed the history of this facility with Art Johnson and me.

## Layout and Operations

The Diesel Oil Sales storage facility occupies approximately 0.3 acre west of the town of Winslow (Figure 9). On the western border of the site lies a ravine that leads 500 feet south to Eagle Harbor.

The facility is used as a fuel (heating) oil storage and transfer station. Included are:

- four storage tanks
- tanker truck transfer dock
- ditch and catch basin

A high fence with a locking gate encloses the facility. The tanks and loading areas stand upon natural substrate--no containment walls are present. The ditch runs from the transfer dock/tank area to the catch basin.

## Historical Review

The fuel storage site was the scene of an oil spill in February 1975. The incident brought about the construction of the ditch and catch basin. The basin is designed to contain an accidental spill.

Aldis (1984) reported the Diesel (Standard) Oil Sales Company transferred oil from barges to storage tanks at the foot of Madison Street from 1940 to 197/. The Winslow Wharf Marina now occupies that dock site (Figure 9). Recent EPA (1984b) aerial photographs suggest the presence of other storage tanks at the Diesel Oil Sales office on Madison Street; these were not inspected.

### DISCUSSION AND CONCLUSION

Other than the single oil spill incident in 1975, little is known of any past problems with the Diesel Oil Sales facility. The current facility we visited was probably constructed in the late 1960s or early 1970s.

Also, WDOE has no record of spills emanating from the older site at the foot of Madison Street. The old barge unloading dock has been torn down and a marina (Winslow Wharf) has been built at the site. However, the City of Winslow sewage treatment plant outfall was located in the same vicinity from 1950 - 1973 (Aldis, 1984).

Results from subtidal sediment samples collected by EPA in April 1984 may be able to show if PNAs are present in the area. However, if PNAs are present, it will be difficult to discern their major source(s). Heating oil, diesel, and gasoline have similar PNA concentrations (Table 1). Also, used motor oil, often found in municipal effluents, has several PNAs. However, these sources of PNAs are minor compared to creosote oil (Table 1).

Further investigations should use the sediment sample results for direction and scope.

JJ:cp

cc: Dave Wright, NWRO
John Littler, WDOE
Dave Tetta, USEPA




Figure 9. The location of the Diesel Oil sales Storage site and office site in relation to Eagle Harbor and vieinity.

	Heating Oil	Diesel Oil	Gasoline	High- octane Gasoline	Used Motor Oil	Creosote
Anthracene	1-6.7	2.9	one con		Office Section	1,500
Phenanthrene	ND	ND	tion and			10,700
Benzo(a)anthracene	0.02-0.06	0.13	<0.5-1.0	11.5	2.2	dina distr
Pyrene	<0.45-3.0	0.37	0.15-5.1	10.6	11.6	2,200
Fluoranthene	<0.47-3.6	0.57	0.06-3.2	10.8	-	3,400
Chrysene	0.37-0.81	0.45	<0.54-0.57	4.9	China basin	3,100
Benzo(a)pyrene	0.01-0.05	0.07	0.03-0.55	6.2	2.4	200
Benzo(e)pyrene	<0.01-0.02	0.18	0.03-0.85	2	2.7	
Benzo(g,h,i)perylene	0.01-0.07	0.03	0.04-1.4	6.4	1.8	

<sup>1</sup>Petroleum data summarized from Table 2.5, page 50 of Health Impacts of Polynuclear Aromatic Hydrocarbons, 1981 A.W. Pucknat, ed., Noyes Data Corp. Park Ridge, NJ. Creosote data summarized from Characteristics of Wood-Preserving Creosote by Physical and Chemical Methods of Analysis, 1974. USDA Forest Service Research Paper FPL 195, Madison. WI, pg. 31; and Table 2.17, page 69 of Pucknat, 1981.

### REFERENCES

- Adams, M., 1972. Various phone conversation and meeting notes by N.W. Regional Office WDOE inspector with Don Johnson of the Wyckoff Company dated 9/20, 11/10, 11/15, 1972.
- Aldis, 1984. Potential UHWS, Eagle Harbor, WA Memo to John Osborn, USEPA, from Ecology and Environment, Inc. March 14, 1984.
- Allworth, N.D., 1972. "Report on Creosote Seepage at Eagle Harbor" and cover letter to the Wyckoff Company dated October 23, 1972. Harbinger, Inc., Bellevue, WA. 7 pp
- Anon, 1957. Pollution Control Commission Industrial Waste Effluent Studies report. March 25, 1957.
- Army service Map, 1944. Collection held in WDOE S.W. Regional Office of Water Resources Section.
- Bainbridge Review, 1959. Advertisement for Baxter-Wyckoff Company products in September 1959 edition.
- Baker, C., 1981. Letter to Mr. A. Potts, Chief Appraiser of Kitsap County Assessors Office dated February 3, 1981.
- Bowen, E.T., R. Kvelstad, E. Parfitt, F. Perry, and V. Stott, 1971. <u>Kitsap</u> <u>County History</u> Dinner & Klein, Seattle, WA. 704 pp
- Cunningham, R.K., 1984. "Eagle Harbor" memorandum to John Bernhardt, Wash. St. Dept. of Ecology, Olympia, WA, April 9, 1984.
- Dehn, W.T., 1972. "Abatement of Creosote Seepage at Eagle Harbor Plant" report by CH<sub>2</sub>M Hill to Wyckoff Company. September 29, 1972. Bellevue, WA. 11 pp
- DNR, 1980. Lease No. 10735 from the Wash. Dept. Natural Resources for the Wyckoff Company, issued October 14, 1980.
- EPA, 1984a. Results of well testing reported at a public meeting in Winslow, WA. July 1984.
- EPA, 1984b. Photographic Analysis of Uncontrolled Waste Site in Mukilteo, Yacolt and winslow, WA. U.S. Environmental Protection Agency, Monitoring Systems Laboratory, Las Vegas, NV.
- Fuentes, R., 1983. U.S. Environmental Protection Agency Draft Report on Uncontrolled Hazardous Waste Site Project: the Wyckoff Company-Bainbridge Island Plant. U.S. EPA, Seattle, WA.
- Huntley, G.B., 1957. Letter from West Coast Wood Preserving Co. superintendent to S. Knox of Pollution Control Commission, December 3, 1957.
- Johnson, D., 1972. Letter to Mr. James Willman of U.S. Environmental Protection Agency, Region X, Seattle, dated August 28, 1972.

- Johnson, D., 1981. Letter from Wyckoff Company engineer to Craig Baker of N.W. Regional Office, Wash. St. Dept. of Ecology. May 19, 1981.
- Jones, K., 1952a. Letter from Pollution Control Commission inspector to Wm. Smoker of Dept. of Fisheries, December 31, 1952.
- Jones, K. 1952b. Memorandum to Pollution Control Commission files. December 31, 1952
- Joy, J., 1984. "Eagle Harbor Investigations: Project Proposal" memorandum to Bill Yake, Wash. St. Dept. Ecology, Olympia, WA. May 9, 1984
- Knox, S., 1957. Pollution Control Commissio industrial inspection memorandum of September 3, 1957.
- Knox, S, 1958. Pollution Control interoffice memorandum to files. February 11, 1958.
- Knox, S. 1961. Pollution Control Commission interoffice memorandum to files and D. Ness of April 25, 1961.
- Knox, S. 1962. Pollution Control Commission interoffice memorandum to files June 11, 1962.
- Knox, S. 1961. Pollution Control Commission interoffice memorandum to files and B.M. Johnson of December 11, 1963.
- Malins, D., 1984. Letter to Dr. Gary O'Neal from Director of Environmental Conservation Div., NOAA/NMFS Seattle, WA, dated March 19, 1984.
- Merriott, E.F., 1941. <u>Bainbridge through Bifocals</u>. Gateway Printing, Seattle, WA. 292 pp.
- Nielson, L., 1953. Industrial inspection memorandum of the Pollution Control Commission to files, August 11, 1953.
- Nielson, L., 1959. Pollution Control Commission interoffice memorandum to Art Garton, C.V. Gibb, and files. June 4, 1959.
- Pacific Testing Laboratories, 1972. Log notes for nine wells drilled at Creosote, WA.
- Sceva, J.E., 1957. Geology and Groundwater Resources of Kitsap Co., WA. U.S. Geological Survey Water Supply Paper 1413. U.S. Dept. of Interior, Washington D.C., 177 pp.
- Stoddard, C., 1984. Wyckoff Company engineer, telehone conversation on July 30, 1984.
- S.W. Regional Staff, 1984. Conversations with Jon Neel, Rick Pierce, and Darrel Anderson in Olympia, WA. July 1984.